

2007 UPDATES CABIN AIR FILTERS



HERE'S TO CLEAN, FRESH AIR!

- Filter both **recirculated** and **fresh air**.
- Work to **minimize circulation** of unwanted particles in the passenger compartment.
- **Capture dust, pollen** and other **unwanted airborne particles**.

VEHICLE	MODEL YEAR	ENGINE	SERVICE REPLACEMENT FILTER NO.	FILTER TYPE	WARRANTY REPAIR FILTER NO.	FILTER TYPE	CASE NO.
AVALON	2000-04	1MZFE*	87139-YZZ05	EE	87139-06030	EE	88899-06020
	2005-07	2GRFE	87139-YZZ08	EE	87139-07010	HEP	88899-07010
CAMRY/HV	2002-04	1MZFE, 2AZFE, 3MZFE	87139-YZZ05	EE	87139-06030	EE	88899-06020
	2005-06	1MZFE, 2AZFE, 3MZFE	87139-YZZ05	EE	87139-06030	EE	88899-06020
	2007	2AZFE, 2GRFE (NAP)	87139-YZZ08	EE	87139-07010	HEP	88899-07010
	2007	2AZFXE (HV)	87139-YZZ08	EE	87139-07010	HEP	88899-33040
CELICA	2000-05	1ZZFE, 2ZZGE*	87139-47010-83	P	87139-47010-83	P	88899-06020
COROLLA/MATRIX	2003-07	1ZZFE, 2ZZGE	88568-02020	EE	88568-02020	EE	88548-02030
ECHO	2000-05	1NZFE*	88568-52010-83	P	88568-52010-83	P	88548-52010
FJ CRUISER	2007	1GRFE	87139-47010-83	P	87139-47010-83	P	88899-06020
HIGHLANDER/HV	2001-07	2AZFE, 1MZFE, 3MZFE*	87139-48020-83	P	87139-48020-83	P	88899-30870
	2006-07	3MZFE (HV)	87139-48020-83	P	87139-48020-83	P	88899-30870
	2008	V6 (2GRFE)	87139-YZZ08	EE	87139-52020	EE	-----
LAND CRUISER	2006-07	2UZFE	88568-60010	P	88568-60010	P	-----
PRIUS	2001-07	1NZFXE	87139-47010-83	P	87139-47010-83	P	88899-47010
RAV4	2001-05	1AZFE, 2AZFE	88568-52010-83	P	88568-52010-83	P	88899-42090
	2006-07	2AZFE, 2GRFE	87139-YZZ08	EE	87139-52020	EE	88548-42020
SIENNA	2004-05	3MZFE (XLE)	87139-YZZ05	EE	87139-06030	EE	88899-06020
	2004-05	3MZFE (LE)	87139-47010-83	P	87139-47010-83	P	88899-06020
	2006-07	3MZFE	87139-YZZ05	EE	87139-06030	EE	88899-06020
SOLARA	2002-07	1MZFE, 3MZFE, 2AZFE	87139-YZZ05	EE	87139-06030	EE	88899-06020
TACOMA	2005-07	1GRFE, 2TRFE	87139-YZZ09	P	88508-01010	P	-----
4RUNNER	2003-07	1GRFE, 2UZFE	87139-47010-83	P	87139-47010-83	P	88899-06020
TUNDRA	2007	1GRFE, 2UZFE, 3URFE	87139-YZZ08	EE	87139-07010	HEP	-----
YARIS	2006-07	1NZFE	87139-YZZ08	EE	87139-52020	EE	88548-52040
SCION xA	2004-06	1NZFE*	88568-52010-83	P	88568-52010-83	P	88548-52010
SCION xB	2004-06	1NZFE*	88568-52010-83	P	88568-52010-83	P	88548-52010
	2008	2AZFE	87139-YZZ08	EE	87139-52020	EE	-----

The Scion tC cannot be retrofitted with a Cabin Air Filter or Case Part Number due to cooling system operations.

P – Pollen Filter: The standard filter designed to capture larger particles including pollen, dust, and other allergens.
 EE – Electrostatic Filter: While it functions like a Pollen Filter, it also holds a static charge that captures smaller particles such as asbestos and tire dust.
 HEP - High Efficiency Pollen: Features a 2 layer filtering structure (Pollen and Electrostatic materials) that helps to capture more particles.

*Retrofits available – inspect vehicle to determine if filter and case are needed.
 Avalon XL
 Celica – all grades
 ECHO
 Highlander (2001-04)
 Scion xA
 Scion xB

